

8th & Plutus Streets Pottery



Chester Hancock County WV

Photos by START Region III

TDD SW3 02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 10 30 AM North

Description Photo shows ceramic debris pile on the south end of the property



START Huggins 5/17/02 10 40 AM West

Description Oil well and tank at top of slope near ceramic debris pile

AR100012

8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III

TDD SW3-02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 10 48 AM West

Description View of Ohio River from the south west corner of the site



START Huggins 5/17/02 10 55 AM South East

Description Bluish powder like material possibly one of the batch materials used at this facility

AR100013


8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III

TDD SW3 02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 11 10 AM North East

Description View of interior of main building showing graffiti



START Huggins 5/17/02 11 15 AM West

Description View of interior of main building showing graffiti

AR100014

8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III


TDD SW3 02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 11 20 AM Down

Description Black carbon like material spilled on floor of building



START Huggins 5/17/02 11 22 AM East

Description Empty drums staged inside building

AR100015

8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III

TDD SW3-02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 11 30 AM Down

Description Batch hopper located on upper floor



START Huggins 5/17/02 11 35 AM West

Description Ceramics stock still remaining inside building

AR100016

8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III

TDD SW3 02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 11 38 AM North

Description Open gate that does not restrict access to property



START Huggins 5/17/02 11 40 AM East

Description Rotting sections of upstairs floor

AR100017


8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III


TDD SW3 02 07-0016

Project # 001262 0278 01SI



START Huggins 5/17/02 11 42 AM

Description Brake pads staged on floor of building



START Huggins 5/17/02 11 45 AM East

Description Transformers located near the center of the property outside the building

AR100018

8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III

TDD SW3 02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 11 50 AM West

Description Resident of property on north end – using a utility garage as a home



START Huggins 5/17/02 11 55 AM North West

Description Apartment complex located across the street from the property

AR100019

8th & Plutus Streets Pottery

Chester Hancock County WV

Photos by START Region III

TDD SW3 02 07 0016

Project # 001262 0278 01SI



START Huggins 5/17/02 12 10 PM North

Description Extent as waste pile as seen from underneath the
Rt 50 bridge

AR100020